

# Die Cast Lock - ADC Series

1. Insert cable into rectangular hole (designated by arrow).  
*Note: Be careful when handling the cable ends. if they're frayed, they can become very sharp.*
2. Feed cable through the hole and into the second rectangular hole (also designated with arrow).
3. Press the lock to increase/decrease the size of the loop.
4. To remove cable, press the locks and pull the cable out (not shown).

