

Perfex™ Hanging Signframe Kits

1. Slide corner brackets into frame with raised indentation facing outwards (fig. A).
2. Press firmly into place.
3. Slide graphic through open slot on side of frame (fig. B).
4. Determine hanging option.

Applicable Products:

PX1, PX2, PX3, PX4,
PX5, PX6

