200-SP

- 1. Insert frame adapter into CR200 channel (fig. A).
- 2. Hook frame adapter in between pop up frame intersection (fig. B).
- 3. Insert plug and turn on.





